

SECRET

OUT52997

S E C R E T 172148Z

25X1

1. CAMERA B 7 WAS USED IN MISSION 3751 FLOWN ON 15 OCTOBER; ~~FOR~~
PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

18 OCT 1963

HPS

2. ORIGINAL NEGATIVE:

CJS

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

GFC

B. 9L SIDE: A SERIES OF MINUS DENSITY DOTS, 1.5" APART AND 2.1" FROM THE OUTBOARD EDGE, ARE PRESENT THROUGHOUT. THERE ARE SCRATCHES, MINOR IN SIZE AND RANDOMLY SPACED BETWEEN FRAMES 528 AND 569. FRAME 1143 ALSO CONTAINS A SMALL SCRATCH. MINOR OUTBOARD EDGE FOG IS PRESENT FROM FRAMES 1331 TO FRAMES 1463.

HPS

LOL

Grace (File)

C. 9R SIDE: THERE ARE RANDOM MINOR PROCESSING STREAKS THROUGHOUT. THERE ARE 7 HEAT SPLICES WITH ASSOCIATED HANDLING MARKS BETWEEN FRAMES 1729 AND 1862.

D. THERE WERE NO CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES ON THIS MISSION. THERE ARE A TOTAL OF 2094 EXPOSURES PER SIDE.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE POSITIVES ARE GOOD.

B. CLOUDS COVERED 15-20 PERCENT OF THE MISSION.

S E C R E T

END OF MESSAGE

1

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification